

The fundamentals for safe working is good housekeeping.

Obstacles, clutter and materials lying around can not only cause a fire, but could also lead to slipping, tripping and falling.

GOOD PRACTICE

- ✓ A clean and tidy working area. (Deck, engine room)
- ✓ Electricity cabinets are free from materials.
- ✓ Stairs and (emergency) exits are clean and free from obstacles.
- ✓ Storing used rags or cloths in closed steel bins/buckets.
- ✓ Fix oil leakages immediately.
- ✓ Remove redundant grease, especially with moving parts.
- ✓ Store materials and tools in the cabinets intended for that purpose.
- ✓ Keep paint in closed drums and storage separately.



BAD PRACTICE

- x Clutter, dirt and materials lying around on deck and in engine rooms.
- x Ignoring oil leakages.
- x Keeping paint open in drums in the working area.
- x Leave obstacles on and/or nearby stairs and (emergency) exits..



ACTIEVRAGEN

- What are the hazards of bad housekeeping?
- Where can we store used rags and cloths? Keep in mind the danger of the cloths heating up.
- Are there enough facilities to store tools and products?

